

Massachusetts Department of Environmental Protection Bureau of Resource Protection – Watershed Permitting Program Sanitary Sewer Overflow (SSO)/Bypass Notification Form

Comments

FOR DEP USE ONLY

Tax Identification Number

A.	Reporting Facility				
	Facility Information			MA0101231	
Re	porting Sewer Authority			Permit #	
2.	Authorized Representative Trans	nsmitting Form:			
Ar	am		Varjabedian	781-925-0906	
Fir	st Name		Last Name	Telephone No.	
	ant Manager			avarjabedian@woodardcurran.com	
Tit	le			E-mail Address	
В.	Phone Notifications:				
1.	MassDEP staff contacted: Contacted By	Email	<u>David</u> First Name	Burns Last Name	
2.	Date/Time contacted: Contacted by: EPA staff contacted: Contacted by:	Email	06/13/2018 07:55 AM David First Name	Turin Last Name	
2	Date/Time EPA contacted: Board of Health contacted:		06/13/2018 07:55 AM	 Sullivan	
3.	Contacted by:	Email	Joyce First Name	Last Name	
	Date/Time contacted:		06/13/2018 07:55 AM	_	
4.	Dir of Wastewater Oper. Hull S Contacted by:	ewer Dept. contacted: Phone	John First Name	Struzziery Last Name	
	Date/Time contacted:		6/12/2018 9:10	_	
5.		nservation Agent - Chr		of Marine Fisheries - Ryan Joyce,Hull Dow,Town Manager - Philip Lemnios	



Notification Form

Massachusetts Department of Environmental Protection Bureau of Resource Protection – Watershed Permitting Program Sanitary Sewer Overflow (SSO)/Bypass

Details: Lime applied to all areas with spreader.

C. SSO Information 1. SSO Discovered: Date and Time 06/12/2018 08:00 AM By: Dave Wilson, Jim Gagliard 2. SSO Stopped Date and Time 06/12/2018 08:30 AM Pump Station, Other Sanitary Manhole, Pump Station, Backup into property, Other - Specify Below 3. SSO Discharge from: Specify: At Pump Station A, from broken drain back valve which is part of the pump station bypass system. Sewage came up through the valve gat 4. SSO Discharge to: Ground Surface Ground Surface, Direct to Receiving Water, Catch Basin to Receiving Water, Backup into Basement Specify: Location: 42 Valley Beach Rd. Hull, MA (Description of discharge site or closest address) X,Y Coordinates 42.26793; -70.846246 5. Estimated SSO Volume at time of this Report: Less than 50 gallons Method of Estimating Volume: Visual Other Method: 6. Cause of SSO Event: Other - Specify Below Rain Event, PS Failure, Insufficient Capacity in System, Treatment Unit failure , Sewer System Blockage, Pipe Collapse, Root Intrusion, Grease Blockage, Other Specify: Broken drain back valve that broke during valve exercise - preventive maintenance task. Able to stop the overflow. Lime applied to all surface areas, since water had evaporated very quickly. Contractor notified to 7. Corrective Actions: perform repairs on next day [6/13/18]. Impact Area cleaned and/or disinfected: Corrective Actions Completed:



Massachusetts Department of Environmental Protection

Bureau of Resource Protection – Watershed Permitting Program

Sanitary Sewer Overflow (SSO)/Bypass Notification Form


D. Comments/Attachments/Follow-up

Additional comments and planned actions:

See attached


I wish to provide the following:

Attachement, Additional Comments











Massachusetts Department of Environmental Protection

Bureau of Resource Protection - Watershed Permitting Program

Sanitary Sewer Overflow (SSO)/Bypass **Notification Form**

E. Certification Statement

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

6/16/2018 Signature of Authorized Representative Date Signed


Please keep a copy of this report for your records. When submitting additional information, include the MassDEP Incident Number from this report.

MassDEP Regional Office and EPA Telephone and Fax Numbers:

Fax: 978-694-3499 Northeast Phone: 978-694-3215 508-947-6557 Southeast Phone: 508-946-2750 Fax: Central Re Phone: 508-792-7650 508-792-7621 Fax: 413-784-1149 Western F Phone: 413-784-1100 617-918-0870 EPA Cont Phone: 617-918-1870 Fax:

DEP 24-h: Phone: 888-304-1133

061218 - Pump Station A



Esri, HERE, Garmin, INCREMENT P, NGA, USGS

0.01

0.01

0.03 km






6-12-18 LIME APPLIED TO ALL AREAS

gate Box for drambach

VALLEY BEACH Rd







REPAIRED DER VALVE
AFTER REPAIRS G-13-18

Town of Hull Wastewater Treatment Plant

1111 Nantasket Avenue Hull, MA 02045 (781) 925-1207



NPDES Permit # MA0101231

Unauthorized Discharge Summary Pump Station [LS A] [6-12-18]

Location (address or latitude and longitude);	On SSO form
Date and Time unauthorized discharge began;	On SSO form
Date and Time unauthorized discharge stopped;	On SSO form
Source of the notification (e.g., property owner, field crew, police);	Staff at location performing preventive maintenance on station valves – exercising & also upgrading bypass hook-up connections.
Type of asset from which the unauthorized discharge occurred (e.g., station, manhole, main);	Drain back valve which is part of the station bypass piping system failed and leak resulted coming up through gate box onto the ground and surrounding area.
Estimated gallons released;	Estimated at less than 50 gallons. Sewage spilled onto the ground and asphalt. Staff able to keep much of the sewage contained and directed back toward the wet well manhole, but some sewage did spill onto area asphalt.
Method used to estimate volume;	Best estimate based upon visual.
Cause of the unauthorized discharge, (blockage or break; mechanical, electrical, or structural failures);	Failure of drain back valve
If caused by a blockage, identify the type of blockage (e.g., grease, rags, debris);	NA NA
If caused by a mechanical, electrical, or structural failure, the date of the last inspection, maintenance, or repair of the failed asset;	Component used approximately 3 months earlier on 3/13/18.
Did the release reach any portion of the Town's Municipal Separate Storm Sewer System ("MS4").	No release to MS4; no storm drains in this area.

If the release occurred to the ground, provide the location of the nearest down-gradient catch basin and the name of the receiving water to which the catch basin discharges;	No near-by down-gradient catch basins. Leak was adjacent to pump station.
Did the release reach a wetland or surface water?	No
If so, include the name and exact location where?	
Measures taken to minimize the volume and duration of the unauthorized discharge;	Noted above and on SSO form. Diverted/diked sewage back to the wet well manhole.
Measures taken to clean the area where the unauthorized discharge occurred;	Lime applied to all areas; repairs made the following day.
Corrective actions taken to prevent reoccurrence of unauthorized discharges at the same location;	New valve installed on 6/13/18
Date of the last unauthorized discharge in the same general location;	3/13/18



42.2679393 -70.8462464







PASTE MAP LINK

Please use Pick Location button or touch on the map if you need more accurate location

